

GOVT. OF WEST BENGAL IRRIGATION & WATERWAYS DIRECTORATE Office of the Superintending Engineer Mahananda Barrage Circle

Teesta Administrative Building Tinbattimore, Siliguri District- Darjeeling Pin 734005.

EOI No:.

/19 - 20 / Mahananda Barrage Circle

On line Expression of interest is invited from the interested parties with experience in doing the similar work as below.

"Underwater Inspection: & survey of structural damage at Fulbari of Mahananda Barrage (at Upstream) (203.80M) and Mahananda Aqueduct at Hoptiagach (370M) & Barang Aqueduct (144 M) at Baishvita in semi dry condition. & preparation of DPR" for repairing the same.

Mahananda Barrage & Mahananda Aqueduct & Barang Aqueduct are 3 major hydraulic structures have distress of concrete components & leakage through joints.

Scope of the work: Activities shall broadly include; A) Underwater inspection. B)Survey of the extent of damage C) Test of damage of concrete floor & structural component. (D) Repairing the same with necessary materials. & (E) Preparation of DPR

The party shall quote rate with GST and statutory taxes in the attached format.

For Clarification Contact: Superintending Engineer, Mahananda Barrage Circle at – 87685 – 96469.

(Krishnendu Bhoumik) Superintending Engineer Mahananda Barrage Circle

Format

E01	for	Wo	rk"

(i) Name of the Firm
--

(ii) Address :

(iii) Contact No.:

(iv) E-mail Id:

(v) Past experience (with client's name of the work & Amount)

(i)

(ii)

(* Attach Certificate)

(vi) Details of the Offer:-

Items	Unit	Rate	Amount
didupa na sa sa	luntenna obnu	mant i secues e	Seption III
		againmuterny alay	He of referr
		and the	densati alle
			DECEMBER 11-11-P
			Estalla v
material desirence			
0			
			REUR PLANE

Signature