

Memo No. **745**

1<sup>st</sup> **CORRIGENDUM NOTICE AGAINST S.N.I.T. No.- 03 / CID OF 2020-21.**

Date. **18/09/2020**

Due to some unavoidable circumstances the following changes (Sl.No. 01 to 24) are made in connection with SNIT No.- 03/CID OF 2020-21  
Circulated vide this office Memo No.- 725 Dated 15.09.2020.

Sl No	Name of works	Amount put to Tender	Earnest Money	(Instead of)		(To be read as)	
				Name of works	Amount put to Tender	Name of works	Amount put to Tender
1	Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 55 mtr. near the house of Swapan Nayak, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist- Purba Medinipur.	1933083.00	38662.00	Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 55 mtr. near the house of Swapan Nayak, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist- Purba Medinipur.	1921288.00	38426.00	
2	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 50 mtr. near the house of Rakhal Nayak, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist- Purba Medinipur."	1929851.00	38597.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 50 mtr. near the house of Rakhal Nayak, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist- Purba Medinipur."	1919128.00	38383.00	
3	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 70 mtr. near the hosue of Kalyan Maity, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist- Purba Medinipur."	1931426.00	38629.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 70 mtr. near the hosue of Kalyan Maity, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist- Purba Medinipur."	1916414.00	38328.00	
4	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 50 mtr. near the hosue of Rameswar Jana, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist- Purba Medinipur."	1926207.00	38524.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 50 mtr. near the hosue of Rameswar Jana, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist- Purba Medinipur."	1915485.00	38310.00	
5	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 54 mtr. near the hosue of Jhareswar Jana, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist- Purba Medinipur."	1886337.00	37727.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 54 mtr. near the hosue of Jhareswar Jana, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist- Purba Medinipur."	1874756.00	37495.00	

	Name of works	Amount put to Tender	Earnest Money	Name of works	Amount put to Tender	Earnest Money
6	" Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 110 mtr. near the house of Sunil Nayak, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1892589.00	37852.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 110 mtr. near the house of Sunil Nayak, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1868999.00	37380.00
7	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 50 mtr. near the hosue of Pravakar Shit, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1921251.00	38425.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 50 mtr. near the hosue of Pravakar Shit, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1910528.00	38211.00
8	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 95 mtr. near Sheetaala Temple, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1936624.00	38732.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 95 mtr. near Sheetaala Temple, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1916251.00	38325.00
9	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 55 mtr. near Moon Hotel, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1924934.00	38499.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 55 mtr. near Moon Hotel, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1913139.00	38263.00
10	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 65 mtr. near DSDA electric post no. 67, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1896360.00	37927.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 65 mtr. near DSDA electric post no. 67, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1882421.00	37648.00
11	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 63 mtr. near the house of Gouranga De, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1915797.00	38316.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 63 mtr. near the house of Gouranga De, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1902286.00	38046.00
12	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 100 mtr. near hotel Samudra Sathi, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1902120.00	38042.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 100 mtr. near hotel Samudra Sathi, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1880675.00	37614.00
13	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 47 mtr. near Hotel Rai, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1916921.00	38338.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 47 mtr. near Hotel Rai, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1906841.00	38137.00
14	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 45 mtr. near Bishnupada Jana house, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1941363.00	38827.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 45 mtr. near Bishnupada Jana house, Mouza- Chandpur in G.P. Talgachari-II, Block- Ramnagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.. "	1931712.00	38634.00

	Name of works	Amount put to Tender	Earnest Money	Name of works	Amount put to Tender	Earnest Money
15	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 50 mtr. near Sudhir Barik house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1887972.00	37759.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 50 mtr. near Sudhir Barik house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1877249.00	37545.00
16	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 50 mtr. near DSDA electric post no. 90, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1907609.00	38152.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 50 mtr. near DSDA electric post no. 90, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1896886.00	37938.00
17	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 70 mtr. near Babu Majhi house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1896260.00	37925.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 70 mtr. near Babu Majhi house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1881249.00	37625.00
18	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 110 mtr. near Gourhari Das house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1867189.00	37344.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 110 mtr. near Gourhari Das house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1843599.00	36872.00
19	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 80 mtr. near Chitto Das house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1908647.00	38173.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 80 mtr. near Chitto Das house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1891491.00	37830.00
20	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 100 mtr. near Jiban Das house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1901125.00	38023.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 100 mtr. near Jiban Das house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1880041.00	37601.00
21	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 70 mtr. near Jharu Jana house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1910337.00	38207.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 70 mtr. near Jharu Jana house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1895325.00	37907.00
22	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 120 mtr. near Ajit Dolui house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1921603.00	38432.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 120 mtr. near Ajit Dolui house, Mouza- Chandpur in G.P. Talgachari-II, Block- Rannagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur.."	1895868.00	37917.00

No.	Name of works	Amount put to Tender	Earnest Money	Name of works	Amount put to Tender	Earnest Money
23	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 60 mtr. near Harijan Primary School, Mouza- Chandpur in G.P. Talgachari-II, Block- Rammagar-I, P.S.- Mandarmoni Coastal and Dist.-Purba Medinipur."	1918080.00	38362.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 60 mtr. near Harijan Primary School, Mouza- Chandpur in G.P. Talgachari-II, Block- Rammagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur."	1905213.00	38104.00
24	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 100 mtr. near DSDA electric post no. 45, Mouza- Chandpur in G.P. Talgachari-II, Block- Rammagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur."	1897882.00	37958.00	"Emergent restoration work of sea-dyke damaged by severe wave action due to excessive rise of wave height during New Moon Kotal for a length of 100 mtr. near DSDA electric post no. 45, Mouza- Chandpur in G.P. Talgachari-II, Block- Rammagar-I, P.S.- Mandarmoni Coastal and Dist.- Purba Medinipur."	1876436.00	37529.00

All other terms and conditions remain unchanged.

Page 4/4

Memo no.- 745(1/9)

Copy forwarded for information and wide circulation to the :-

1. Chief Engineer - South-West, I&W.Dte. Khasiangal, Midnapore, Paschim Medinipur
2. Superintending Engineer, Western Circle, III, I&W.Dte. Tamluk, Pura Medinipur.
3. Sub-Divisional Officer/Digha/Contai/Egra/Etamogra (I) Sub-Division, (I&W.Dte) Pura Medinipur
4. Office Notice Board/Divisional Account Officer/ Estimating Section, Contai Irrigation Division.

Date:- 18.09.2020

*whm 18.9.20*

(Tender Inviting Authority)

Executive Engineer,

Contai Irrigation Division (I&W. Dte.)

Contai, Purba Medinipur

*whm 18.9.20*

Executive Engineer,

Contai Irrigation Division (I&W. Dte.)

Contai, Purba Medinipur

**FORM 1****APPLICATION FOR TENDER***(To be typed in company letter pad)*

To

*The Executive Engineer  
 Contai Irrigation Division (I.W & Dte.)  
 Contai, Purba Medinipur*

Notice Inviting Tender No:- .....

Serial No. of Work applied for:- .....

Amount Put to Tender:- Rs. ....

Dear Sir,

Having examined the Statutory, Non statutory & NIT documents, I / We hereby like to state that I / We willfully accept all your conditions and offer to execute the works as per Tender No. and Serial No. stated above. I / We also agree to remedy the defects after / during execution of the above work in conformity with the conditions of contract, specifications, drawing, bill of quantities and addenda.

Dated this ..... day of ..... 2020

Full name of applicant: .....

Signature: .....

In the capacity of: .....

Duly authorized to sign bids

For &amp; on behalf of (name of Firm): .....

(In block capitals)

Office address:

Telephone no(s) (office): .....

Mobile No. ....

Fax No. ....

E- mail ID: .....

**FORM 2****Declaration against Common Interest***(To be typed in company letter pad)*

I / We, Sri / Smt. ...., the authorized signatory on behalf of ..... do hereby affirm that I / We / any of the member of ..... bidding against NIT No. .... Sl. No. .... do not have any common interest either as a partner on any partnership firm / consortium as a Proprietor / Owner of any other firm in the same serial for the work I / We want to participate.

.....  
Signature of bidder

**Enclosure:**

- i) PAN Card / Income Tax, Sales Tax and Professional Tax Clearance Certificate from appropriate authority valid beyond the date of opening of Tender.
- ii) Technical Credential
- iii) Partnership Deed in case of Partnership Firm.
- iv) Registration papers, current audit report, (at least up to the 2<sup>nd</sup> last years preceding the current one), copy of Bye-laws, No Objection Certificate of A.R.C.S. in case of Registered Engineers Co-operatives.
- v) Statement showing similar nature of works successfully completed during last five years.
- vi) Contractors participated in the NIT must produce the GST Registration Certificate.