

## GOVT. OF WEST BENGAL IRRIGATION & WATERWAYS DIRECTORATE Office of the Superintending Engineer Mahananda Barrage Circle

Teesta Administrative Building Tinbattimore, Siliguri District- Darjeeling Pin 734005.

EOI No:. 🖔 🛴 /19 - 20 / Mahananda Barrage Circle

On line Expression of interest is invited from the interested parties with experience in doing the similar work as below.

"Underwater Inspection: & survey of structural damage at Fulbari of Mahananda Barrage (at Upstream) (203.80M) and Mahananda Aqueduct at Hoptiagach (370M) & Barang Aqueduct (144 M) at Baishvita in semi dry condition. & preparation of DPR" for repairing the same (2<sup>nd</sup> call).

Mahananda Barrage & Mahananda Aqueduct & Barang Aqueduct are 3 major hydraulic structures have distress of concrete components & leakage through joints.

**Scope of the work:** Activities shall broadly include; A) Underwater inspection. B)Survey of the extent of damage C) Test of damage of concrete floor & structural component. (D) Repairing the same with necessary materials. & (E) Preparation of DPR.

The party shall quote rate with GST and statutory taxes in the attached format.

Last date of submission is 16/07/2019 upto 16.00 hrs at this office in prescribed format.

For Clarification Contact: Superintending Engineer, Mahananda Barrage Circle at – 87685 – 96469.

(Krishnendu Bhoumik)
Superintending Engineer
Mahananda Barrage Circle

## **Format**

F <sub>0</sub>	1 f	or	1/1	or	レ"

(i	No.	ime c	of the	Firm:
----	-----	-------	--------	-------

(ii) Address :

(iii) Contact No.:

(iv) E-mail Id:

(v) Past experience (with client's name of the work & Amount)

(i)

(ii)

(\* Attach Certificate)

(vi) Details of the Offer:-

Items	Unit	Rate	Amount
hoho pela - i			
age Technique			te Paper.

Signature

Firms Name & Seal